Lat = 41 05 17 Flood Stage = 6 ft

The Total Number of Floods by Month Bush Kill at Shoemakers, PA Period of Record 1956 - 2001

Lon = $75\ 02\ 17$ Number of Floods = 4

Month	Number of Floods
January	2
February	0
March	0
April	0
May	0
June	0
July	1
August	0
September	0
October	0
November	0
December	1
Month	Number of Floods